


# STANDARD ROCKER SWITCH WIRING DIAGRAM

**240v SUPPLY TO  
SWITCHED FUSED SPUR**



**PLEASE ALWAYS REFER TO THE WIRING DIAGRAM SUPPLIED WITH  
YOUR ACTUATORS/MOTORS.**

**ENSURE THAT THE CORRECT VOLTAGE IS BEING USED FOR THE  
MOTORS YOU ARE FITTING.**